

| T x W x L (mm)    | Material  | Pin Material | Pin Size (mm) | Outer Dia (mm) | Surface                | Hole Distance (mm) | Knuckle (mm) |
|-------------------|-----------|--------------|---------------|----------------|------------------------|--------------------|--------------|
| 0.9*19* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.5         |
| 0.9*25* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.5         |
| 0.9*27* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.5         |
| 0.9*28.5* 50-2100 | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.5         |
| 0.9*30* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.5         |
| 0.9*32* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.5         |
| 0.9*38* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.5         |
| 0.9*44* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.5         |
| 0.9*50* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.5         |
| 1.2*32* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.7         |
| 1.2*38* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.7         |
| 1.2*50* 50-2100   | SS / Iron | SS / Iron    | 3             | 5              | SS / User Requirements | User Requirements  | 12.7         |
| 1.5*32* 50-2100   | SS / Iron | SS / Iron    | 4.5           | 7.5            | SS / User Requirements | User Requirements  | 25           |
| 1.5*38* 50-2100   | SS / Iron | SS / Iron    | 4.5           | 7.5            | SS / User Requirements | User Requirements  | 25           |
| 1.5*50* 50-2100   | SS / Iron | SS / Iron    | 4.5           | 7.5            | SS / User Requirements | User Requirements  | 25           |
| 1.5*57* 50-2100   | SS / Iron | SS / Iron    | 4.5           | 7.5            | SS / User Requirements | User Requirements  | 25           |

|                   |           |           |     |     |                        |                   |    |
|-------------------|-----------|-----------|-----|-----|------------------------|-------------------|----|
| 1.5*63* 50-2100   | SS / Iron | SS / Iron | 4.5 | 7.5 | SS / User Requirements | User Requirements | 25 |
| 1.5*76* 50-2100   | SS / Iron | SS / Iron | 4.5 | 7.5 | SS / User Requirements | User Requirements | 25 |
| 1.5*127* 50-2100  | SS / Iron | SS / Iron | 4.5 | 7.5 | SS / User Requirements | User Requirements | 25 |
| 2.0*38* 50-2100   | SS / Iron | SS / Iron | 6   | 10  | SS / User Requirements | User Requirements | 25 |
| 2.0*50* 50-2100   | SS / Iron | SS / Iron | 6   | 10  | SS / User Requirements | User Requirements | 25 |
| 2.0*57* 50-2100   | SS / Iron | SS / Iron | 6   | 10  | SS / User Requirements | User Requirements | 25 |
| 2.0*63.5* 50-2100 | SS / Iron | SS / Iron | 6   | 10  | SS / User Requirements | User Requirements | 25 |
| 2.0*76* 50-2100   | SS / Iron | SS / Iron | 6   | 10  | SS / User Requirements | User Requirements | 25 |
| 2.0*101* 50-2100  | SS / Iron | SS / Iron | 6   | 10  | SS / User Requirements | User Requirements | 25 |
| 2.0*127* 50-2100  | SS / Iron | SS / Iron | 6   | 10  | SS / User Requirements | User Requirements | 25 |
| 3.0*38* 50-2100   | SS / Iron | SS / Iron | 6   | 12  | SS / User Requirements | User Requirements | 25 |
| 3.0*50* 50-2100   | SS / Iron | SS / Iron | 6   | 12  | SS / User Requirements | User Requirements | 25 |
| 3.0*57* 50-2100   | SS / Iron | SS / Iron | 6   | 12  | SS / User Requirements | User Requirements | 25 |
| 3.0*63.5* 50-2100 | SS / Iron | SS / Iron | 6   | 12  | SS / User Requirements | User Requirements | 25 |
| 3.0*76* 50-2100   | SS / Iron | SS / Iron | 6   | 12  | SS / User Requirements | User Requirements | 25 |
| 3.0*101* 50-2100  | SS / Iron | SS / Iron | 6   | 12  | SS / User Requirements | User Requirements | 25 |
| 3.0*127* 50-2100  | SS / Iron | SS / Iron | 6   | 12  | SS / User Requirements | User Requirements | 25 |